


# Wood Destroying Insect Inspection Report

Notice: Please read important consumer information on **page 2.**

<b>Section I. General Information</b> Inspection Company, Address, & Phone <b>A Full House Inspection Co. LLC</b> <b>530 Prospect Avenue</b> <b>Little Silver, NJ 07739</b> <b>732-758-9887</b>	Company's Business Lic. No.	Date of Inspection <b>5/24/2008</b>
	Address of Property Inspected <b>123 Main Street</b> <b>Anytown, NJ 07777</b>	File Number:

Inspector's Name, Signature, & Certification, Registration, or Lic. # <b>Peter W. Bennett</b> 	Structure(s) Inspected <b>Single Family Residence &amp; Garage</b>
---	---

**Section II. Inspection Findings** This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. **Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:**

- A. No visible** evidence of a wood destroying insect infestation was observed.
- B. Visible** evidence of a wood destroying insect infestation was observed as follows:
  - 1. Live insects (description and location):  
**right rear corner of the crawlspace ( intact termite shelter tubes and wood boring beetle holes )**
  - 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location):
  - 3. **Visible** damage from wood destroying insects was noted as follows (description and location):  
**sillplate at rear rear corner of crawlspace**

**NOTE: This is not a structural damage report.** If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.

Yes  No It appears that the structure(s) or a portion thereof may have been previously treated. Evidence of previous treatment:  
**plugged drill holes/borings consistent with conventional termite treatment in the landing of the front steps**

The inspecting company can give no assurances with regard to work by other companies. The company that performed the treatment should be contacted for information on treatment and any warranty or service agreement which may be in place.

**Section III. Recommendations**

No treatment recommended: (Explain if Box B in Section II is checked)

Recommended treatment for the control of:  
**TERMITES AND WOOD BORING BEETLES**

**Section IV. Obstructions & Inaccessible Areas**  
The following areas of the structure(s) inspected were obstructed or inaccessible:

- Basement
- Crawlspace **24,**
- Main Level **1, 3, 4, 8, 9, 11,**
- Attic **1, 3, 4, 5, 11, 24,**
- Garage **4, 6, 7, 9, 11, 24,**
- Exterior
- Porch
- Addition
- Other

- The inspector may write out obstructions or use the following optional key:**
- |                         |  |
|-------------------------|--|
| 1. Fixed ceilings       | 13. Only visual access                 |
| 2. Suspended ceiling    | 14. Cluttered condition                |
| 3. Fixed wall covering  | 15. Standing water                     |
| 4. Floor covering       | 16. Dense vegetation                   |
| 5. Insulation           | 17. Exterior siding                    |
| 6. Cabinets or shelving | 18. Window well covers                 |
| 7. Stored items         | 19. Wood pile                          |
| 8. Furnishings          | 20. Snow                               |
| 9. Appliances           | 21. Unsafe conditions                  |
| 10. No access or entry  | 22. Rigid foam board                   |
| 11. Limited access      | 23. Synthetic stucco                   |
| 12. No access beneath   | 24. Duct work, plumbing, and/or wiring |

**Section V. Additional Comments and Attachments** (these are an integral part of the report)  
**Review with the seller about the past inspection/treatment records, any existing warranty or service plan, and associated damage/repairs, if any. Conduct annual WDI inspection with a licensed pest control operator**

Attachments \_\_\_\_\_

**Signature of Seller(s)** or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage repair and treatment history has been disclosed to the buyer

X

**Signature of Buyer.** The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.

X

# Important Consumer Information Regarding the Scope and Limitation of the Inspection

Please read this entire page as it is part of this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

**1. About the Inspection:** A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. **For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or non-insect wood destroying organisms.** This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. **This shall not be construed as a 90 day warranty.** There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.

**2. Treatment Recommendation Guidelines Regarding Subterranean Termites:** FHA and VA require treatment when any active evidence of subterranean termites is found in a structure. If signs of subterranean termites -but no activity- are found in a structure that shows no evidence of having been treated for subterranean termites in the past, then a treatment should be recommended. A treatment may also be recommend for a previously treated structure showing evidence of subterranean termites -but no activity- if there is no documentation of a liquid treatment by a licensed pest control company within the previous five years unless the structure is presently under warranty or covered by a service agreement with a licensed pest control company.

**3. Obstructions and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions, nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If an area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.

**4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects.** Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s) landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.

**5. Neither the inspection company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.**